

Message Text

UNCLASSIFIED

PAGE 01 HONG K 01226 031340Z

43

ACTION SY-04

INFO OCT-01 ARA-10 EUR-12 EA-10 NEA-09 ISO-00 /046 W

----- 005679

R 030644Z FEB 75

FM AMCONSUL HONG KONG

TO SECSTATE WASHDC 3701

AMEMBASSY BEIRUT

AMEMBASSY PANAMA

AMCONSUL FRANKFURH

UNCLAS HONG KONG 1226

DEPT FOR A/SY/T

BEIRUT, PANAMA AND FRANKFURT FOR RTC

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: HAZARD ON MK II PAN/TILT SYSTEM

REF: SAIGON 994 NOTAL

PAN/TILT SYSTEM DELIVERED WITH MK II CONCORD CAMERA HAS HAZARD WHICH HAS LED TO THE BURN OUT OF DAMPING RESISTOR ON TWO OF THE THREE UNITS RECEIVED HERE TODATE. PRINTED CIRCUIT BOARD FOR RIGHT/LEFT CONTROL OF PAN HAS 100 OHM RESISTOR; IN NEAR CONTACT TO RESISTOR IS BRAIDED CABLE LEADING TO MOTOR. AFTER UTILIZATION RESISTOR BURNS OUT EITHER DUE TO UNDER-RATING OR TO BRAID COMING IN CONTACT WITH ELEMENTS ON PRINTED CIRCUIT BOARD. WOULD QUESTION RELIABILITY OF THESE UNITS UNTIL DESIGN FAULT FULLY IDENTIFIED.
CROSS

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 03 FEB 1975
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Authority: n/a
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1975HONGK01226
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D750038-0924
From: HONG KONG
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1975/newtext/t19750278/aaaacsqh.tel
Line Count: 45
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION SY
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 1
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: 75 SAIGON 994
Review Action: RELEASED, APPROVED
Review Authority: CunninFX
Review Comment: n/a
Review Content Flags:
Review Date: 23 APR 2003
Review Event:
Review Exemptions: n/a
Review History: RELEASED <23 APR 2003 by MarshK0>; APPROVED <07 JAN 2004 by CunninFX>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
05 JUL 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: HAZARD ON MK II PAN/TILT SYSTEM
TAGS: ASEC
To: STATE
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 05 JUL 2006